

SLACK ADJUSTERS



TABLE OF CONTENTS

1	SLACK ADJUSTERS		
	SPECIFICATIONS		
2	CROSS-REFERENCE		
	CROSS-REFERENCE		

WARRANTY

Alliance Truck Parts are backed by a 1-year/unlimited kilometre standard warranty.





SLACK ADJUSTERS



SLACK ADJUSTER FAILURE

Proper brake stroke adjustment and maintenance are critical to roadway safety.

- Measure chamber stroke by checking the distance from the chamber to the pin with the brakes released vs. full brake application. Ensure that this distance is within maximum allowable specifications for your vehicle
- If an automatic slack adjuster has excessive chamber stroke, do not manually adjust it. Over-stroking is usually a sign of adjuster failure or a larger problem with the braking system
- Light-duty braking cycles are a common cause of brake over-stroking. If insufficient torque passes through the adjuster, it may not cause the ratchet within the adjuster to advance. If this continues, the automatic slack adjuster is no longer compensating for the normal wear of the brakes
- Recommended: On a regular basis, make a few full-pressure brake applications to cause the adjuster to turn over, and then visually check the stroke before leaving the yard

SPECIFICATIONS



GUNITE STYLE



HALDEX STYLE



MERITOR STYLE



CREWSON STYLE

SLACK ADJUSTER SPECIFICATIONS					
PART NUMBER	SPECIFICATIONS				
QABP N42AS R801079	1-1/2"-28 spline, 5.5" arm length - MERITOR STYLE				
QABP N42ASAS1140	1-1/2"-28 spline, 5.5" arm length - GUNITE STYLE				
QABP N42ASAS1172	1-1/2"-28 spline, 5.5" arm length without clevis - GUNITE STYLE				
QABP N42AS 40020231	1-1/2"-28 spline, 5.5" arm length - HALDEX STYLE				
QABP N42AS 42106	1-1/2"-28 spline, 6.0" arm length, 5/8"-18str CREWSON STYLE				
QABP N42AS 42100	1-1/2"-28 spline, 5.5" arm length, 5/8"-18str CREWSON STYLE				

Alliance automatic slack adjusters include clevis unless otherwise noted.





2

CROSS-REFERENCE



CREWSON		
COMP. P/N	ALLIANCE P/N	
BRU 42100	ABP N42AS 42100	
BRU 42106	ABP N42AS 42106	

GUNITE		
COMP. P/N	ALLIANCE P/N	
AS1140	ABP N42AS AS1140	
AS1172	ABP N42AS AS1172	

HALDEX		
COMP. P/N	ALLIANCE P/N	
40020231	ABP N42AS 40020231	

MERITOR		
COMP. P/N	ALLIANCE P/N	
16-13840-000	ABP N42AS R801079	



FIND YOUR NEAREST LOCATION AT ALLIANCETRUCKPARTS.CO.NZ







Mercedes-Benz is a registered trademarks of Daimler AG, Stuttgart Germany. Freightliner and Alliance Truck Parts are registered trademarks of Daimler Trucks North America LLC, all distributed by Daimler Truck and Bus Australia Pacific Pty Ltd. ACN 618 413 282 / NZCN 8039364. Specifications are subject to change without notice.

 $\label{thm:copyright} \textbf{@ Daimler Truck and Bus Australia Pacific Pty Ltd. All rights reserved.}$